



Electric Motor Testing Tip of the Week

revolutionizing *electrical* reliability

October 15, 2007

The Seven-step Process for Basic Electrical Troubleshooting

Step six of the seven-step troubleshooting approach is *Verify the Repair*. Verifying the repair includes:

- Ensuring the equipment is operating as designed
- Performing another round of tests focusing on the quality of the repair and reliability of the system
- Verifying no new discrepancies have appeared resulting from the repair

To read more about this step and see it applied to a boiler feed pump example, read the Basic Electrical Troubleshooting document at <http://www.pdma.com/pdfs/Articles/Troubleshooting.pdf>.

You are invited to submit an Electric Motor Testing Tip of your own and receive a free PdMA mug or hat if we publish it! Contact Lou at 813-621-6463 ext. 126 or lou@pdma.com.