



Tip Of The Week

October 10, 2011

Platinum Plus - A South African Success Story

Have you ever been deep underground in a mine? Have you wondered what would happen if the pump keeping the water from flooding the mine failed without warning? The warning signs are there, but it takes a proper motor testing program to predict pump problems and take action to prevent motor failure...and a flooded mine.

View this Case Study (http://www.pdma.com/webinars/Cracked_Rotor_bars/Cracked_Rotor_Bar.html) to learn how MCEMAX™ prevented catastrophic motor failure in a South African platinum mine.

Next week we will resume the series on basic electrical troubleshooting with *Identifying the Source of the Problem*.

You are invited to submit an Electric Motor Testing Tip of your own and receive a free PdMA mug or hat if we publish it! Contact Lou at 813-621-6463 ext. 126 or lou@pdma.com.

Copyright 2011 PdMA Corporation. All rights reserved. The PdMA Tip of the Week is produced by PdMA. PdMA shall not be liable for any errors or delays in the content, or for any actions taken in reliance thereon.