



Tip Of The Week

February 13, 2012

Motor Received From Rewind, Now What?

After receiving a motor from the rewind shop, it is advisable to perform precision resistance readings like those available from the MCE Standard Test. Any increase in phase resistance of a three phase induction motor from the baseline test or original design will have a detrimental effect on the motor efficiency. To learn more about identifying defects related to the power circuit and how they might affect the performance and reliability of your motor go to:
http://www.pdma.com/webinars/Power_Circuit_Fault_Zone/powercircuit.html

You are invited to submit an Electric Motor Testing Tip of your own and receive a free PdMA mug or hat if we publish it! Contact Lou at 813-621-6463 ext. 126 or lou@pdma.com.

Copyright 2012 PdMA Corporation. All rights reserved. The PdMA Tip of the Week is produced by PdMA. PdMA shall not be liable for any errors or delays in the content, or for any actions taken in reliance thereon.