
December 11, 2017

Three Strikes And You're Out!

The final tip of 2017 is a reminder that there are *three* fundamental elements of electric motor reliability.

- Power Quality – Verification and validation that a new or refurbished motor is in good condition on acceptance.
- Trending – Historical data for comparison to identify changes or trends in the data that could identify anomalies.
- Troubleshooting – Maximizing technology and resources to quickly and efficiently troubleshoot and isolate the cause of a faulty motor or generator to minimize downtime.

Missing one or two of these fundamental elements may keep you in the game. If you miss all three elements you will surely strike out in electric motor reliability. To watch a video describing the three fundamentals of electric motor reliability visit the PdMA YouTube Channel at: <https://www.youtube.com/watch?v=gpGYV7yYOJ8>

NOTE: Due to the holiday season, this will be the last Tip of the Week until January 8, 2018.

You are invited to submit an Electric Motor Testing Tip of your own and receive a free PdMA[®] mug or hat if we publish it! Contact Lou at 813-621-6463 ext. 166 or lou@pdma.com.