



A Leader in Electric Motor Testing

Tip Of The Week

December 17, 2018

Test Your Knowledge - Part 3

For the remainder of 2018, our Tip of the Week will consist of a true/false question presented to the Tip of the Week recipients.

After pushing the start button on an AC induction squirrel cage motor, the motor begins rotating but trips after 20 seconds failing to reach full load speed. After a visual inspection and resetting of the overloads a second attempt fails in the same way. The most likely cause of the motor tripping is a turn-turn short in the stator windings. True or False.

Click here to check your answer http://www.pdma.com/12-17-18_Part3.php

You are invited to submit an Electric Motor Testing Tip of your own and receive a free PdMA® mug or hat if we publish it! Contact Lou at 813-621-6463 ext.166 or lou@pdma.com.

Copyright 2018 PdMA® Corporation. All rights reserved. The PdMA Tip of the Week is produced by PdMA. PdMA shall not be liable for any errors or delays in the content, or for any actions taken in reliance thereon.