



Electric Motor Testing Tip of the Week

revolutionizing *electrical* reliability

November 12, 2007

Backing Up MCEGold Calibration Files

We recommend that you back up the MCEGold calibration files located on the computer. Although there is a back-up located in the Windows directory, it is recommended that you copy the files into some sort of external media (CD, Memory Stick, Flash Drive, Zip Drive, Company Server, etc.).

The original calibration files are located in:

C:\Program Files\PdMA Corporation\MCEGold\Emax\EmaxCal.xml

C:\Program Files\PdMA Corporation\MCEGold\Mce\MCECal.xml

You are invited to submit an Electric Motor Testing Tip of your own and receive a free PdMA mug or hat if we publish it! Contact Lou at 813-621-6463 ext. 126 or lou@pdma.com.

Copyright 2007 PdMA Corporation. All rights reserved. The PdMA Tip of the Week is produced by PdMA. PdMA shall not be liable for any errors or delays in the content, or for any actions taken in reliance thereon.