



Tip Of The Week

December 6, 2010

For the remainder of 2010, our Tip of the Week will consist of a question presented to the Tip of the Week recipients.

Question for December 6: True or False - From the book *Maintenance and Reliability Best Practices*, written by Ramesh Gulati, the following three criteria are recommended for selecting the best key performance indicator/metrics:

- should encourage the right behavior
- should be difficult to manipulate
- should be easy to measure.

The correct answer is true.

If you answered incorrectly and feel you need additional training OR if you answered correctly and still feel you need additional training, we can help you. Our training department offers classes on various topics, click here (<http://www.pdma.com/PdMA-training.php>) to go to the training page. We also have a Data Interpretation Book available to help you. Contact PdMA (pdma@pdma.com) or call (813) 621-6463 for information.

You are invited to submit an Electric Motor Testing Tip of your own and receive a free PdMA mug or hat if we publish it! Contact Lou at 813-621-6463 ext. 126 or lou@pdma.com.

Copyright 2010 PdMA Corporation. All rights reserved. The PdMA Tip of the Week is produced by PdMA. PdMA shall not be liable for any errors or delays in the content, or for any actions taken in reliance thereon.