

January 9, 2012

Strive for Excellence in 2012

To help you reach excellence in testing in 2012, here is a list of things you can do to be more efficient:

- Make a checklist(s)
- Create a weekly/daily watchlist or test route
- Plan your travel accordingly, whether your visiting several locations or walking through one plant
- Verify your test equipment daily – verify tester batteries and computers are fully charged and keep chargers nearby, check your test leads for issues
- Evaluate and verify the test location/area ahead of time
- Bring the proper tools and PPE the first time
- Get additional training, know how to operate your test equipment properly
- Don't rush, but have a pace
- Communicate well with others
- Most importantly...BE SAFE

You are invited to submit an Electric Motor Testing Tip of your own and receive a free PdMA mug or hat if we publish it! Contact Lou at 813-621-6463 ext. 126 or lou@pdma.com.