



A Leader in Electric Motor Testing

Tip Of The Week

October 13, 2014

Knowledge is Power

Step one of the seven step troubleshooting procedure is to **Gather Information**. There are many things that should be evaluated during this step like technical documentation, system knowledge, and trended data. However, there is one key aspect that should not be overlooked and that is comparing the data between like motors. This comparison can be very valuable and necessary prior to being able to complete step four- **Identifying the Source of the Problem**. To show how one customer put theory to practice and used his knowledge of trouble shooting, please view the following presentation:

http://www.pdma.com/webinars/Pump_Case_Study/Pump_Case_Study.html

You are invited to submit an Electric Motor Testing Tip of your own and receive a free PdMA® mug or hat if we publish it! Contact Lou at 813-621-6463 ext. 126 or lou@pdma.com.

Copyright 2014 PdMA® Corporation. All rights reserved. The PdMA Tip of the Week is produced by PdMA. PdMA shall not be liable for any errors or delays in the content, or for any actions taken in reliance thereon.