



Tip Of The Week

June 27, 2011

Remember the Basics

The more comfortable and familiar we get in our facilities sometimes we overlook doing things properly. It's always good to slow down a bit and re-evaluate our safe working techniques.

While working with any test equipment, always remember to connect the ground wire first. It not only contributes to a safe working environment for the technician, it also ensures that your test equipment will not be subject to a potentially damaging situation.

You are invited to submit an Electric Motor Testing Tip of your own and receive a free PdMA mug or hat if we publish it! Contact Lou at 813-621-6463 ext. 126 or lou@pdma.com.

Copyright 2011 PdMA Corporation. All rights reserved. The PdMA Tip of the Week is produced by PdMA. PdMA shall not be liable for any errors or delays in the content, or for any actions taken in reliance thereon.